


TEX-QD

Quick Disconnect Fittings



FEMALE BY HOSE BARB WITH O-RING:

I.D.	Part Number	A Dim.	B Dim.	C Dim.	Lbs./Each
2"	2.0-QDF-SP	2.0"	3.75"	5.25"	0.75
3"	3.0-QDF-SP	3.0"	5.25"	7.0"	1.75
4"	4.0-QDF-SP	4.0"	8.0"	10.5"	3.30
6"	6.0-QDF-SP	6.0"	8.5"	10.5"	6.40
8"	8.0-QDF-SP	7-58/64"	9.25"	13"	12.70
With Locking Lever Welded On					
10"	10.0-QDF-SP	9-56/64"	11.5"	15.75"	28.00
12"	12.0-QDF-SP	11-56/64"	11.5"	16.5"	39.00

MALE BY HOSE BARB:

I.D.	Part Number	A Dim.	B Dim.	C Dim.	Lbs./Each
With Locking Lever Welded On					
2"	2.0-QDM-SP	2.0"	3.75"	6.25"	1.65
3"	3.0-QDM-SP	3.0"	5.25"	8.25"	3.35
4"	4.0-QDM-SP	4.0"	8.0"	12.5"	7.10
6"	6.0-QDM-SP	6.0"	8.5"	12.5"	14.15
8"	8.0-QDM-SP	7-58/64"	9.25"	15.0"	21.15
Lever Welded on Female End					
10"	10.0-QDM-SP	9-56/64"	11.5"	15.75"	25.0
12"	12.0-QDM-SP	11-56/64"	11.5"	6.5"	35.0